

1A



1B



1A: View from GCC towards the front of the lab facility.
1B: Paved parking at the rear of the lab.

Date
Dec. 03, 2008

Photo Plate
1

Plus Plus

2A



2B



2A: Interior of lab facility.

2B: Central corridor showing final preparation for painting.

Date
Dec. 03, 2008

Photo Plate
2

Plus Plus

3A



3B



3A: Vehicle processing bay where interior furnishings are being staged for installation.

3B: Continued work on mechanical and electrical on pad at the front of the lab

Date
Dec. 03, 2008

Photo Plate
3

Flux Pite

**GUAM POLICE DEPARTMENT
CONSTRUCTION OF FORENSICS LABORATORY**

Inspection Report

Date: December 3, 2008

Time: 3:15 pm

Name: Joel Sablan

Work In Progress:

Landscaping and fence installation, HVAC duct work and mechanical/electrical work, interior finishing, painting, construction debris removal, interior fixtures and furniture installation.

Discussions/Meetings:

None

Eddie Guiao – Asanuma Project Engineer was unavailable for an interview during two site visits and telephone calls. Project is close to completion.

Action Items/Follow-up Issues:

None. Photographs attached
