

**GUAM POLICE DEPARTMENT  
CONSTRUCTION OF FORENSICS LABORATORY**

Inspection Report

Date: 6/10/2008

Time: 0905

Name: Joel Sablan

Work In Progress:

- installing metal joists in metal deck main floor level
- preparing pre cast panels for walls
- continuation of backfilling underground conduit exterior lighting

Discussions/Meetings:

Interviewed Eddie Guico - Project Engineer  
No major issues at this time.

Action Items/Follow-up Issues:

None  
Pictures attached

1A



1A: View from the entrance to the lab facility showing pre-cast panel installation on the ground floor extending the length of the facility.

Date  
June 10, 2008

Photo Plate  
1

**Plus Plus**

2A



2B



2A: Pre-cast wall panels braced during installation at the north end of the lab.  
2B: View from the northeast.

Date  
June 10, 2008

Photo Plate  
2

**Plus Plus**

3A



3B



3A: Structural steel reinforced floor at main level.

3B: Structural steel members.

Date  
June 10, 2008

Photo Plate  
3

**Plus Plus**

4A



4B



4A: Installation of a storm water manhole.

4B: View from the southwest, scale of the new facility is now apparent.

Date  
June 10, 2008

Photo Plate  
4

**Plus Plus**