

**GUAM POLICE DEPARTMENT
CONSTRUCTION OF FORENSICS LABORATORY**

Inspection Report

Date: July 14th, 2008

Time: 3:00 pm

Name: Joel Sablan

Work In Progress:

- Erection of pre-cast walls (interior)(exterior) Grid 10-14.
- Installation of metal decking (roof)
- Installation of copper water pipes
- Installation of sewer line (6")

Discussions/Meetings:

- Installation of electrical panel outlet boxes and switches.
- Forming of precast for gutters.

Interview w/ Eddie Guico - Asunomas project engineer.

Action Items/Follow-up Issues:

None

1A



1B



1A: View from GCC showing the lab facility and ongoing crane installation of pre-cast wall panels.

1B: Installation of metal roofing deck system, north end of new lab facility.

Date
July 14, 2008

Photo Plate
1

Flux Pite

2A



2B



2A: Sheet metal roofing deck material staging area.
2B: Crane positioned to install internal pre-cast walls.

Date
July 14, 2008

Photo Plate
2

Fluor

3A



3B



3A: Crane hoisting of internal pre-cast wall.

3B: Western face (front) of new lab facility, external walls in place.

Date
July 14, 2008

Photo Plate
3

Plus Plus

4A



4A: View from the west of front of new lab facility.

Date
July 14, 2008

Photo Plate
4

Plus Plus